

<b>BILLET CLUTCH LIFTER SET</b>	APPLICATION : GROM (JC61)
CODE : ( BILLET CLUTCH LIFTER SET ) 307-1444600	
( REINFORCED CLUTCH SPRING SET ) 307-1432600	( BILLET CLUTCH LIFTER ) 307-1444690
Reference : Special tools are required to disassemble / install manual clutch. Refer to manufacturer Honda service manual when installation.	

• Thank you for purchasing Kitaco product. Read and understand the instruction before installing.

#### ■ ATTENTIONS (MUST READ)

- BILLET CLUTCH LIFTER SET is designed and made exclusive for GROM, do not use on other models.
- Do not modify the way which is not listed or it will cause damage and trouble.
- We are not responsible for damages and accidents caused by assembling mistake and improper setting.
- Please ask authorized mechanic for assembling and setting.
- Ask a specialist at specialty shop if you do not understand the role of the surrounding parts.
- Do not modify the way which is not listed or it will cause damage and trouble.
- Refer to the manufacturer HONDA service manual when installation.
- Please contact a mechanic nearby immediately when you find something unusual.
- Metal and resin products get stain and deteriorates strength, across the ages.

#### ▼ SPECIALLY MANUFACTURED

60% reinforced springs are included for smooth clutch work.  
Reinforcing 30% is possible, by using 3 Kitaco springs & 3 stock springs at the same time.  
Billet clutch lifter plate is made from aluminum machined with hard alumite finish for high durability.

#### ※ ATTENTION !

Place Kitaco reinforced springs on the plate where bolts are placed, when using 3 stock bolts (M6 X 20) together.  
Make sure that the springs are NOT in the gap between clutch lifter plate and pressure plate.

SPECIALIZED TOOL	CODE	PACKING LIST	
		NAME	QTY
CENTER LOCK NUT WRENCH	674-1432900	REINFORCED CLUTCH SPRING SET	6
GEAR HOLDER	674-0510900	BILLET CLUTCH LIFTER	1



**KITACO**  
株式会社キタコ  
3-8-13 NAGATA,  
HIGASHI-OSAKA,  
OSAKA, 577-0015,  
JAPAN  
<http://www.kitaco.co.jp/>

<b>BILLET CLUTCH LIFTER SET</b>	APPLICATION : GROM (JC61)
CODE : ( BILLET CLUTCH LIFTER SET ) 307-1444600	
( REINFORCED CLUTCH SPRING SET ) 307-1432600	( BILLET CLUTCH LIFTER ) 307-1444690
Reference : Special tools are required to disassemble / install manual clutch. Refer to manufacturer Honda service manual when installation.	

• Thank you for purchasing Kitaco product. Read and understand the instruction before installing.

#### ■ ATTENTIONS (MUST READ)

- BILLET CLUTCH LIFTER SET is designed and made exclusive for GROM, do not use on other models.
- Do not modify the way which is not listed or it will cause damage and trouble.
- We are not responsible for damages and accidents caused by assembling mistake and improper setting.
- Please ask authorized mechanic for assembling and setting.
- Ask a specialist at specialty shop if you do not understand the role of the surrounding parts.
- Do not modify the way which is not listed or it will cause damage and trouble.
- Refer to the manufacturer HONDA service manual when installation.
- Please contact a mechanic nearby immediately when you find something unusual.
- Metal and resin products get stain and deteriorates strength, across the ages.

#### ▼ SPECIALLY MANUFACTURED

60% reinforced springs are included for smooth clutch work.  
Reinforcing 30% is possible, by using 3 Kitaco springs & 3 stock springs at the same time.  
Billet clutch lifter plate is made from aluminum machined with hard alumite finish for high durability.

#### ※ ATTENTION !

Place Kitaco reinforced springs on the plate where bolts are placed, when using 3 stock bolts (M6 X 20) together.  
Make sure that the springs are NOT in the gap between clutch lifter plate and pressure plate.

SPECIALIZED TOOL	CODE	PACKING LIST	
		NAME	QTY
CENTER LOCK NUT WRENCH	674-1432900	REINFORCED CLUTCH SPRING SET	6
GEAR HOLDER	674-0510900	BILLET CLUTCH LIFTER	1



**KITACO**  
株式会社キタコ  
3-8-13 NAGATA,  
HIGASHI-OSAKA,  
OSAKA, 577-0015,  
JAPAN  
<http://www.kitaco.co.jp/>

<b>BILLET CLUTCH LIFTER SET</b>	APPLICATION : GROM (JC61)
CODE : ( BILLET CLUTCH LIFTER SET ) 307-1444600	
( REINFORCED CLUTCH SPRING SET ) 307-1432600	( BILLET CLUTCH LIFTER ) 307-1444690
Reference : Special tools are required to disassemble / install manual clutch. Refer to manufacturer Honda service manual when installation.	

• Thank you for purchasing Kitaco product. Read and understand the instruction before installing.

#### ■ ATTENTIONS (MUST READ)

- BILLET CLUTCH LIFTER SET is designed and made exclusive for GROM, do not use on other models.
- Do not modify the way which is not listed or it will cause damage and trouble.
- We are not responsible for damages and accidents caused by assembling mistake and improper setting.
- Please ask authorized mechanic for assembling and setting.
- Ask a specialist at specialty shop if you do not understand the role of the surrounding parts.
- Do not modify the way which is not listed or it will cause damage and trouble.
- Refer to the manufacturer HONDA service manual when installation.
- Please contact a mechanic nearby immediately when you find something unusual.
- Metal and resin products get stain and deteriorates strength, across the ages.

#### ▼ SPECIALLY MANUFACTURED

60% reinforced springs are included for smooth clutch work.  
Reinforcing 30% is possible, by using 3 Kitaco springs & 3 stock springs at the same time.  
Billet clutch lifter plate is made from aluminum machined with hard alumite finish for high durability.

#### ※ ATTENTION !

Place Kitaco reinforced springs on the plate where bolts are placed, when using 3 stock bolts (M6 X 20) together.  
Make sure that the springs are NOT in the gap between clutch lifter plate and pressure plate.

SPECIALIZED TOOL	CODE	PACKING LIST	
		NAME	QTY
CENTER LOCK NUT WRENCH	674-1432900	REINFORCED CLUTCH SPRING SET	6
GEAR HOLDER	674-0510900	BILLET CLUTCH LIFTER	1



**KITACO**  
株式会社キタコ  
3-8-13 NAGATA,  
HIGASHI-OSAKA,  
OSAKA, 577-0015,  
JAPAN  
<http://www.kitaco.co.jp/>

<b>BILLET CLUTCH LIFTER SET</b>	APPLICATION : GROM (JC61)
CODE : ( BILLET CLUTCH LIFTER SET ) 307-1444600	
( REINFORCED CLUTCH SPRING SET ) 307-1432600	( BILLET CLUTCH LIFTER ) 307-1444690
Reference : Special tools are required to disassemble / install manual clutch. Refer to manufacturer Honda service manual when installation.	

• Thank you for purchasing Kitaco product. Read and understand the instruction before installing.

#### ■ ATTENTIONS (MUST READ)

- BILLET CLUTCH LIFTER SET is designed and made exclusive for GROM, do not use on other models.
- Do not modify the way which is not listed or it will cause damage and trouble.
- We are not responsible for damages and accidents caused by assembling mistake and improper setting.
- Please ask authorized mechanic for assembling and setting.
- Ask a specialist at specialty shop if you do not understand the role of the surrounding parts.
- Do not modify the way which is not listed or it will cause damage and trouble.
- Refer to the manufacturer HONDA service manual when installation.
- Please contact a mechanic nearby immediately when you find something unusual.
- Metal and resin products get stain and deteriorates strength, across the ages.

#### ▼ SPECIALLY MANUFACTURED

60% reinforced springs are included for smooth clutch work.  
Reinforcing 30% is possible, by using 3 Kitaco springs & 3 stock springs at the same time.  
Billet clutch lifter plate is made from aluminum machined with hard alumite finish for high durability.

#### ※ ATTENTION !

Place Kitaco reinforced springs on the plate where bolts are placed, when using 3 stock bolts (M6 X 20) together.  
Make sure that the springs are NOT in the gap between clutch lifter plate and pressure plate.

SPECIALIZED TOOL	CODE	PACKING LIST	
		NAME	QTY
CENTER LOCK NUT WRENCH	674-1432900	REINFORCED CLUTCH SPRING SET	6
GEAR HOLDER	674-0510900	BILLET CLUTCH LIFTER	1



**KITACO**  
株式会社キタコ  
3-8-13 NAGATA,  
HIGASHI-OSAKA,  
OSAKA, 577-0015,  
JAPAN  
<http://www.kitaco.co.jp/>